

CEW011 - EXPERT PACKABLE JACKET

	MEASURING POINTS IN INCHES			XS		S		M		L		XL		XXL		3XL		4XL		TOLERANCE
	GARMENT MEASUREMENTS																			
A	FULL CHEST CIRCUMFERENCE (2" below armhole)			42		44		46		49		52		55		58		61		0,5
D	CB LENGTH			28		29		30		30		31		31		31,5		31,5		0,5
H	SLEEVE LENGTH (from neck point to end of cuff)			31		31,5		32		32,5		33		33,5		34		34,5		0,25